

SUNCHASER VACATION VILLAS FAIRMONT RESORT FAIRMONT HOT SPRINGS, BC

PROGRESS DRAW 15

January 5th, 2015

LTA Consultants Inc.

Professional Quantity Surveyors & Construction Cost Consultants 905 – 1708 Dolphin Avenue Kelowna, BC V1Y 9S4

T: 250-868-8800 F: 888-371-1458

E: <u>lyndon@ltaconsultants.com</u>
W: <u>www.ltaconsultants.com</u>

Prepared for:

Mr. Douglas S Frey
Vice President
Northwynd Resort Properties Ltd.
5799 – 3rd Street SE
Calgary, Alberta T2H 1K1

Table of Contents

1.	PRO	GRESS DRAW 15	3
	1.1	SITE INSPECTION	3 3
	1.2	CONTINGENCY	3
	1.3	GST & PST	4
	1.4	BUILDERS' LIEN HOLDBACK	4
	1.5	DETAILS OF PROGRESS DRAW	4
		1.5.1 Building 8100 (Exterior)	4
		1.5.2 Resort Villa Management Ltd. (RVM) Costs	5
	1.6	STATUTORY DECLARATION & WCB LETTER	5
2.	SCH	EDULE	5
	2.1	CONSTRUCTION SCHEDULE	5
3.	OUT	STANDING INFORMATION	5
	SCH	EDULE A – MASTER BUDGET SUMMARY	
	SCH	EDULE B – SUPPORTING DOCUMENTATION	
	SCH	EDULE C – PROGRESS PHOTOGRAPHS	



1. PROGRESS DRAW 15

1.1 Site Inspection

A site inspection of the project was carried out by our Mr. Brian Anderson on December 17th, 2014, together with Mr. Gary Edwards. At the time of the inspection the temperature on site was approximately -5°C and it was overcast.

Photographs were taken and copies are included with Schedule 'C' of this report.

1.1.1 Building Renovations

Building 8100 (Exterior)

The original porte cochere structure at the front of the building has been removed in its entirety. At the previous connection points of this structure to the building, the natural stone cladding to the stair towers has been reinstated, a stucco band across the third floor balconies has been restored, and various other stucco patching has been completed. (Photos 1 & 2). It is understood that the final stage of this part of the project is to be a repainting of the stucco, which will presumably be carried out after winter conditions have abated.

A concrete band has been placed along the edges of the third floor balconies where the porte cochere roof previously connected (Photos 5 & 6).

A "torch-on" roofing membrane has been applied to the roof of the elevator machine room, although the parapet cap flashings have not yet been installed (Photo 7).

The asphalt paving in the parking lot has been patched where the columns were removed (Photos 3 & 4) as has the concrete slab closer to the building (Photo 8).

The rear patio floors of the ground floor units have been replaced with concrete slabs-on-grade (Photos 9 - 12). The landscaping at the rear of the building has yet to be reinstated and will presumably take place in the spring.

1.1.2 General Comments

The work performed appears to be of satisfactory quality and workmanship. I could not see a rainwater outlet from the elevator machine roof except for the scupper at the front, there may therefore be a collection hopper and a rainwater leader yet to be added.

1.1.3 Consultant Field Reports

There have been no consultant field reports provided for the current progress draw.

1.2 Contingency

The total value of the project contingency remains unchanged in the total sum of \$1,000,000.

Consultants Inc

Page: 3

1.3 **GST & PST**

We note that the Project Budget currently **excludes** HST/GST and PST. As noted in our Initial Report and Budget Review, the revised provincial tax structure will result in an additional 7% being applied to the purchase of materials on the project effective April 1st, 2013. Please refer to our Initial Report dated April 2nd, 2013, for further details regarding the costs associated with the PST on the project.

We note that GST is excluded from our calculations in the Progress Draw Certificates for each building. However, the developer will be required to pay the GST on an ongoing basis.

1.4 Builders' Lien Holdback

We note that under the BC Builders' Lien Holdback Legislation, the developer will be required to retain holdback, and these monies are normally included in the value recommended for payment, so that the developer can set up holdback accounts in accordance with the lien legislation.

1.5 Details of Progress Draw

1.5.1 Building 8100 (Exterior)

This Progress Draw Number 15 is based on actual Hard Cost Construction Work and Project Soft Costs invoiced to December 15th, 2014. Please refer to the Progress Draw Certificate on page 6 of this report for a detailed summary of the current progress draw values.

VVI Construction Ltd. Invoice No. 1449 dated December 15th, 2014, has been submitted for our review and analysis, and develops a total claim value of \$22,218.57 (excluding GST). We have not included GST in our calculation of the current claim value, as GST does not form part of the project budget. Please note, we have not adjusted the current claim to reflect the value of invoices previously paid by Resort Villa Management Ltd. A copy of the invoice has been included in Schedule 'B' of this report.

The invoices submitted to date by VVI Construction Ltd. are summarized as follows:

	Summary of VVI Construction Ltd. Invoices - Building 8100							
		Net Amount		Total				
Date	Invoice #	(Excluding Holdback)	HST/GST	(Excluding Holdback)	Comments			
15-Dec-14	1449	\$22,218.57	\$1,110.93	\$23,329.50	Includes invoices directed to RVM			
Total to	Date	\$22,218.57	\$1,110.93	\$23,329.50				

It can be seen from the 'Comments' section that the current invoice includes values that have been paid directly by Resort Villa Management Ltd. (RVM). According to the invoice provided by VVI Construction Ltd. the total value of invoices to be directed to RVM equates to \$2,814.19 (including GST). We have not deducted the value of these invoices from the current value recommended for payment, as the costs associated with these items form part of the total project budget, and these values need to be included in the calculation for the work completed to date.



Page: 4

1.5.2 Resort Villa Management Ltd. (RVM) Costs

RVM is a subcontractor to the project, and provides goods and services to VVI Construction Ltd. In this Progress Draw Number 15, VVI Construction has approved invoices totalling \$2,814.19 (including GST) that can be directed to RVM for the work completed on building 8100.

1.6 Statutory Declaration & WCB Letter

We have not yet been provided with a copy of the contractor's statutory declaration.

A copy of the WCB Clearance Certificate for VVI Construction Ltd. dated January 3rd, 2015, has been included under Schedule 'B' of this report. The certificate indicates that the account is currently active and in good standing.

2. SCHEDULE

2.1 Construction Schedule

We have not yet been provided with a construction schedule for Building 8100. We will follow up with VVI Construction for a copy of the construction schedule.

3. **OUTSTANDING INFORMATION**

There is no outstanding information at this time.



PROGRESS DRAW NUMBER 15 - BUILDING 8100

PROGRESS DRAW CERTIFICATE - BUILDING 8100				
Original Project Budget (Excluding GST & PST)	\$221,183.00			
Changes to Budget	\$9,217.00			
Revised Project Budget (Excluding GST & PST)	\$230,400.00			
Less: Remaining Available Budget (Variance)	(\$180,202.02)			
Total Work Completed to Date (Excluding GST & PST)	\$50,197.98			
Less: Previous Value Recommended for Payment	(\$25,510.68)			
Less: Deficiency Retention	\$0.00			
Current Work Completed (Excluding GST & PST)	\$24,687.30			
Less: Builder's Lien Holdback @ 10%	(\$2,468.73)			
Current Value Recommended for Payment (Excluding GST & PST)	\$22,218.57			

Notes:

- 1. The above value excludes GST and PST;
- 2. Builders' Lien Holdback has been deducted from the current value recommended for payment as noted above.
- 3. Refer to Schedule 'A' for details regarding the Project Master Summary;
- 4. Refer to Schedule 'B' for a copy of the contractor's invoice and specific details regarding the project budget and current claim for the building.

Lyndon P. Thomas, PQS, MRICS

hyndon Thomas

January 5th, 2015



DRAW SUMMARY – BUILDING 8100

DRAW SUMMARY - BUILDING 8100				
Total Project Pudget	\$230,400.00			
Total Project Budget	\$230,400.00			
Previously Uncertified Claimed Values	\$25,510.68			
Progress Draw Number 15	\$24,687.30			
Total Progress to Date (Including Holdback, Excluding GST & PST)	\$50,197.98			
Remaining Budget Available (Including Holdback, Excl. GST & PST)	\$180,202.02			



Page: 7

SCHEDULE – 'A' MASTER BUDGET SUMMARY





SUNCHASER VACATION VILLAS PROJECT MASTER SUMMARY

5 14	Description Original Budget Changes to		Work Completed to		to Date Remaining Budget		Construction Schedule		
Description	Original Budget	Budget	Revised Budget	\$	%	(Variance)	Start Date	Finish Date	- General Comments
100 Series Buildings									
Building 100	\$1,151,406.00	\$0.00	\$1,151,406.00	\$0.00	0%	\$1,151,406.00	T.B.D.	T.B.D.	
Building 200	\$2,147,297.00	\$0.00	\$2,147,297.00	\$0.00	0%	\$2,147,297.00	T.B.D.	T.B.D.	
Building 300	\$1,964,566.00	\$235,761.00	\$2,200,327.00	\$1,917,408.57	87%	\$282,918.43	November 2013	August 2014	Building 300 is complete.
Building 400	\$2,091,164.00	\$0.00	\$2,091,164.00	\$1,555,481.99	74%	\$535,682.01	March 2013	July 2014	Building 400 is complete.
Building 500	\$1,141,926.00	\$0.00	\$1,141,926.00	\$0.00	0%	\$1,141,926.00	T.B.D.	T.B.D.	
Building 600	\$1,167,408.00	\$0.00	\$1,167,408.00	\$0.00	0%	\$1,167,408.00	T.B.D.	T.B.D.	
Building 700	\$1,261,943.00	\$0.00	\$1,261,943.00	\$0.00	0%	\$1,261,943.00	T.B.D.	T.B.D.	
Building 800	\$1,320,875.00	\$0.00	\$1,320,875.00	\$1,257,911.91	95%	\$62,963.08	April 2013	October 2013	Building 800 is complete.
1000 Series Buildings									
Building 1000	\$2,041,208.00	\$0.00	\$2,041,208.00	\$0.00	0%	\$2,041,208.00	T.B.D.	T.B.D.	
Building 2000	\$2,085,899.00	\$0.00	\$2,085,899.00	\$0.00	0%	\$2,085,899.00	T.B.D.	T.B.D.	
Building 3000	\$2,219,457.00	\$0.00	\$2,219,457.00	\$0.00	0%	\$2,219,457.00	T.B.D.	T.B.D.	
Building 4000	\$2,125,257.00	\$0.00	\$2,125,257.00	\$0.00	0%	\$2,125,257.00	T.B.D.	T.B.D.	
Building 5000	\$1,945,374.00	\$0.00	\$1,945,374.00	\$0.00	0%	\$1,945,374.00	T.B.D.	T.B.D.	
Building 6000	\$2,428,897.00	\$0.00	\$2,428,897.00	\$0.00	0%	\$2,428,897.00	T.B.D.	T.B.D.	
Building 7000 (Upper Levels)	\$2,495,456.00	\$0.00	\$2,495,456.00	\$0.00	0%	\$2,495,456.00	T.B.D.	T.B.D.	
Building 7000 (Basement)	\$733,936.00	\$0.00	\$733,936.00	\$0.00	0%	\$733,936.00	T.B.D.	T.B.D.	
Building 8000	\$2,315,323.00	\$0.00	\$2,315,323.00	\$0.00	0%	\$2,315,323.00	T.B.D.	T.B.D.	
Building 8100	\$353,917.00	\$0.00	\$353,917.00	\$0.00	0%	\$353,917.00	T.B.D.	T.B.D.	
Building 8100 Canopy/Ext.	\$221,183.00	\$9,217.00	\$230,400.00	\$50,197.98	22%	\$221,183.00	01-Nov-14	T.B.D.	
Contingency									
Material Price Contingency	\$1,000,000.00	\$0.00	\$1,000,000.00	\$0.00	0%	\$1,000,000.00	T.B.D.	T.B.D.	
Building Sub-total	\$32,212,492.00	\$244,978.00	\$32,457,470.00	\$4,781,000.45	15%	\$27,717,450.52			
Civil Work									
Sunchaser	\$540,558.00	\$0.00	\$540,558.00	\$0.00	0%	\$540,558.00	T.B.D.	T.B.D.	
Hillside	\$1,642,090.00	\$0.00	\$1,642,090.00	\$0.00	0%	\$1,642,090.00	T.B.D.	T.B.D.	
Riverside	\$146,933.00	\$0.00	\$146,933.00	\$0.00	0%	\$146,933.00	T.B.D.	T.B.D.	
Civil Work - Sub-total	\$2,329,581.00	\$0.00	\$2,329,581.00	\$0.00	0%	\$2,329,581.00			
Total Project Budget	\$34,542,073.00	\$244,978.00	\$34,787,051.00	\$4,781,000.45	14%	\$30,047,031.52			

SCHEDULE – 'B' SUPPORTING DOCUMENTATION





VVI Construction Ltd. PO Box 2988 Revelstoke, BC V0E 2S0 Canada

INVOICE

Page: Date:

December 15, 2014

Invoice No. 1449

Phone:

250-837-2919

Fax:

250-837-6145

Client Ref: Resort Villa Management

Sunchaser Vacation Villas Bldg 8100 Ext.

Ship To:

Bill To:

Resort Villa Management 820 - 59th Ave SE, #100

Calgary, AB T2H 2G5

Canada

403-517-2601

Fax: 403-451-1259

Phone:

Fax:

Salesperson

Project Manager

Tax Exempt No. 1

Tax Exempt No. 2

Registration Number

DAVID

Ship Date

863236402RP0001

12/15/2014

Ship Via

Reference Number

CP # 2

Terms Job

Description

To invoice for:

Sun Chaser Vacation Villa - Building 8100

13523-300

November 1 - December 15, 2014 Division 1 - General Overhead - see summary

13523-300

Division 2 - Sitework - no billings 13523-300 Division 3 - Concrete - see summary

13523-300

Division 4 - Masonry - See summary 13523-300 Division 5 - Metals - See summary

13523-300

Division 6 - Wood & plastics - see summary 13523-300 Division 7 - Thermal Moisture Protection - no billing this month. Division 9 - Finishes - See summary.

13523-300 13523-300

Credit for Invoices Paid by RVM Sun Chaser Invoice # SVV-8100N

13523-300

Balance of this invoice now due: \$ 20,515.31 Credit Applied for Invoices Pd by RSV

Extended Amt.

(\$2,814.19)

\$6,121,24

\$1,376.30

\$5,258.89

\$1,770.00

\$1,993.37

\$2,060.00

\$1,240.00

\$4,867.50

\$0.00

Total:

21,873.11 2,468.73

Sub Total: **GST**

Less Holdback Amount:

19,404.38 \$1,110.93

Invoice Due:

\$20,515.31

Waybill Number:

Invoice Date

12/15/2014

From

9/1/2014

To #######

Sunchaser Vacation Villas Bldg 8100 Ext.

Page: 1 of 1

Billing Report

		Budget	Value Work Done	Previously Claimed	This Progress	Variance
1	DIVISION 1	28,500.00	4,082.85	0.00	4,082.85	24,417.15
	DIVISION 1 Contingency Exterior	20,000.00	0.00	0.00	0.00	20,000.00
	DIVISION 1 Overhead & Fee @%9	18,000.00	4,144.77	2,106.38	2,038.39	13,855.23
2 .	DIVISION 2 - SITEWORK	40,900.00	17,149.98	15,773.68	1,376.30	23,750.02
3	DIVISION 3 - CONCRETE	14,400.00	12,646.24	7,387.35	5,258.89	1,753.76
4	DIVISION 4 - MASONRY	1,800.00	1,770.00	0.00	1,770.00	30.00
5	DIVISION 5 - METALS	1,000.00	1,993.37	3 0.00	1,993.37	(993.37)
6	DIVISION 6 - WOOD & PLASTICS	8,000.00	2,303.27	243.27	2,060.00	5,696.73
7	DIVISION 7 - THERMAL MOISTURE PROT	22,100.00	1,240.00	0.00	1,240.00	20,860.00
8	DIVISION 8 - DOORS & WINDOWS	0.00	0.00	0.00	0.00	0.00
9	DIVISION 9 - FINISHES	75,700.00	4,867.50	0.00	4,867.50	70,832.50
Grand Total:		230,400.00	50,197.98	25,510.68	24,687.30	180,202.02
			Sub Total:		24,687.30	
			Holdback @ 10% o	n Subtotal:	2,468.73	
			Sub Total:		22,218.57	
•			GST @ 5%:		1,110.93	
			Invoice Total :		\$ 23,329.50	
			Invoices paid by R\	/M	(2,814.19)	
			Sub Total:	•	20,515.31	

From 9/1/2014 To 12/15/2014

Sunchaser Vacation Villas Bldg 8100 Ext.

Application 2

Cost Plus Billing Report

Invoice Date 12/15/2014

				Value	Previously	This	
			Budget	Work Done	Claimed	Progress	Variance
Class	1	DIVISION 1					
36		AUTOMOBILE - FUEL	\$400.00	\$0.00	\$0.00	\$0.00	\$400.00
100		HEALTH & SAFETY	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
114		INSURANCE - EQUIPMENT	\$500.00	\$0.00	\$0.00	\$0.00	\$500.00
240		TRAVEL/HOTELS/ACCOMODATIONS	\$500.00	\$0.00	\$0.00	\$0.00	\$500.00
244		ACCOMODATION ALLOWANCE	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
1010		CONTINGENCY	\$20,000.00	\$0.00	\$0.00	\$0.00	\$20,000.00
1041		CONSTRUCTION MANAGEMENT	\$8,000.00	\$1,842.12	\$936.17	\$905.95	\$6,157.88
1043		SUPERVISION	\$10,000.00	\$2,402.50	\$0.00	\$2,402.50	\$7,597.50
1048		CONTRACTORS FEE	\$10,000.00	\$2,302.65	\$1,170.21	\$1,132.44	\$7,697.35
1300		SUBMITTALS	\$500.00	\$0.00	\$0.00	\$0.00	\$500.00
1505		MOBILIZATION	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
1512		TEMPORARY FIRE PROTECTION	\$100.00	\$0.00	\$0.00	\$0.00	\$100.00
1517		TEMPORARY TELEPHONE	\$500.00	\$0.00	\$0.00	\$0.00	\$500.00
1521		FIELD OFFICE & SHEDS & TRAILERS	\$0.00	\$300.00	\$0.00	\$300.00	(\$300.00)
1522		FIRST AID SUPPLIES & LABOUR	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
1530		TEMPORARY CONTRUCTION & HOARDING	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
1540 .		CONSTRUCTION AIDS	\$5,000.00	\$0.00	\$0.00	\$0.00	\$5,000.00
1564		SITE FENCING	\$2,000.00	\$200.00	\$0.00	\$200.00	\$1,800.00
1741		FINAL CLEANING	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
1742		PROGRESS CLEANING/DAILY	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
1745		GARBAGE AND DUMP FEES	\$2,000.00	\$1,180.35	\$0.00	\$1,180.35	\$819.65
1790		DE-MOBILIZATION	\$1,000.00	\$0.00	\$0.00	\$0.00	\$1,000.00
1790		DE-MOBILIZATION	φ1,000.00	φ0.00	\$0.00	φ0.00	\$1,000.00
1 ,		DIVISION 1	66,500.00	8,227.62	2,106.38	6,121.24	58,272.38
Class	2	DIVISION 2 - SITEWORK					
2220		SITE DEMOLITION	\$30,200.00	\$15,773.68	\$15,773.68	\$0.00	\$14,426.32
2222		MINOR SITE DEMOLITION FOR REMODELLING	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2315		EXCAVATION AND BACKFILL	\$10,700.00	\$1,376.30	\$0.00	\$1,376.30	\$9,323.70
2		DIVISION 2 - SITEWORK	40,900.00	17,149.98	15,773.68	1,376.30	23,750.02
Class	3	DIVISION 3 - CONCRETE		· i			······································
3000		CONCRETE	\$0.00	\$4,662.16	\$4,283.45	\$378.71	(\$4,662.16)
3100		CONCRETE FORMS & ACCESSORIES	\$0.00	\$5,784.08	\$3,103.90	\$2,680.18	(\$5,784.08)
3530		CONCRETE TOPPING	\$14,400.00	\$2,200.00	\$0.00	\$2,200.00	\$12,200.00
3		DIVISION 3 - CONCRETE	14,400.00	12,646.24	7,387.35	5,258.89	1,753.76
Class	4	DIVISION 4 - MASONRY					
4400	7	STONE	\$1,800.00	\$1,770.00	\$0.00	\$1,770.00	\$30.00
4		DIVISION 4 - MASONRY	1,800.00	1,770.00	0.00	1,770.00	30.00
Class	5	DIVISION 5 - METALS			······································	<u> </u>	
5520	3	HANDRAILS AND RAILINGS	\$1,000.00	\$1,993.37	\$0.00	\$1,993.37	(\$993.37)
5		DIVISION 5 - METALS	1,000.00	1,993.37	0.00	1,993.37	(993.37)
Class	6	DIVISION 6 - WOOD & PLASTICS		(
6100	J	ROUGH CARPENTRY	\$8,000.00	\$2,303.27	\$243.27	\$2,060.00	\$5,696.73
0100		ROSOH OANFLAHU	<u> </u>				
6		DIVISION 6 - WOOD & PLASTICS	8,000.00	2,303.27	243.27	2,060.00	5,696.73

Class	7	DIVISION 7 - THERMAL MOISTURE P	ROTECTION	1			
7130		SHEET WATER PROOFING	\$12,500.00	\$0.00	\$0.00	\$0.00	\$12,500.00
7300		SHINGLES, ROOF TILES & COVERINGS	\$1,300.00	\$1,240.00	\$0.00	\$1,240.00	\$60.00
7460		SIDING	\$7,100.00	\$0.00	\$0.00	\$0.00	\$7,100.00
7600		FLASHING & SHEET METAL	\$700.00	\$0.00	\$0.00	\$0.00	\$700.00
7714		GUTTERS AND DOWNSPOUTS	\$500.00	\$0.00	\$0.00	\$0.00	\$500.00
7		DIVISION 7 - THERMAL MOISTURE PROTEC	22,100.00	1,240.00	0.00	1,240.00	20,860.00
Class	8	DIVISION 8 - DOORS & WINDOWS					
8100		METAL DOORS & FRAMES	\$0.00	\$0.00	_{/.} \$0.00	\$0.00	\$0.00
8		DIVISION 8 - DOORS & WINDOWS	0.00	0.00	0.00	0.00	0.00
Class	9	DIVISION 9 - FINISHES					
9220		PORTLAND CEMENT PLASTER	\$5,000.00	\$4,867.50	\$0.00	\$4,867.50	\$132.50
9900		PAINTS & COATINGS	\$70,700.00	\$0.00	\$0.00	\$0.00	\$70,700.00
9		DIVISION 9 - FINISHES	75,700.00	4,867.50	0.00	4,867.50	70,832.50
Grand To	otal :		230,400.00	50,197.98	25,510.68	24,687.30	180,202.02
				Sub Total:		24,68	7.30
			Holdback @ 10% on Subtotal:			2,468.73	
				Sub Total:		22,218.57	
				GST @ 5%:		1,11	0.93

GST @ 5%: 23,329.50 Invoice Total: Invoices paid by RVM (2,814.19) 20,515.31 Sub Total:



DATE:

December 15, 2014

INVOICE:

CLIENT:

REGISTRATION #:

CP-2

863236402RP0001 13523-8100

INVOICE

VVI Construction Ltd. PO Box 2988 Revelstoke, BC V0E 2S0 Canada

Phone:

250-837-2919

Fax: 250-837-6145

Sold To:

Resort Villa Management 820 - 59th Ave SE, #100

Calgary, AB T2H 2G5

Canada

Phone: 403-517-2601

Fax: 403-451-1259

Phone :

Ship To:

Fax

1523-8100		100 017 2007				
Cost Type: EQUIPMENT	Ref. Date	Supplier/Employee/Description	Ref/Trade	Hrs/Qt	Type Description Rate	Extended Amt.
10/21/2014 Redeye Rentals & Sales Ltd. 17267 PST 16.8 16.8 10/24/2014 Redeye Rentals & Sales Ltd. 17267 PST 16.8 16.8 10/24/2014 Redeye Rentals & Sales Ltd. 17318 plate tamper rental 50.0 10/24/2014 Redeye Rentals & Sales Ltd. 17318 PST 3.5 3.5 10/31/2014 VIC VAN ISLE CONSTRUCTION LTD 11457 sea can rental 150.0 11/8/2014 Four Season Bobcat & Landscaping 481438 clean up of 8100 building 1,666.0 11/8/2014 Four Season Bobcat & Landscaping 481438 clean up of 8100 building 1,666.0 11/8/2014 HUOLT, SCOTTIE HUO999 7.00 VICVAN 77.50 542.5 11/29/2014 HUOLT, SCOTTIE HUO999 ##### VICVAN 77.50 1,660.0 11/30/2014 Southeast Disposal Ltd 108791 daily waste service Nov 1,180.3 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$1.20 90.5 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$2.0 90.5 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$2.0 90.5 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$2.0 90.5			/illas Bldg 8100 Ext.			
10/21/2014 Redeye Rentals & Sales Ltd. 17287 PST 18.8 10/24/2014 Redeye Rentals & Sales Ltd. 17318 plate tamper rental 50.0 10/24/2014 Redeye Rentals & Sales Ltd. 17318 PST 3.5 10/31/2014 VIC VAN ISLE CONSTRUCTION LTD 11457 sea can rental 150.0 11/8/2014 Four Season Bobcat & Landscaping 481438 clean up of 8100 building 1,066.0 Total : EQUIPMENT FOUR SEASON BOBCATE & LANDSCAPING REDEVISION 1,066.0 Total : EQUIPMENT Total : EQUIPMENT TOTAL : TO	10/21/2014	Redeve Rentals & Sales Ltd.	17267		dynapac tamper rental	240.00
10/24/2014 Redeye Rentals & Sales Ltd. 17318 Plate tamper rental 50.00		•			* * .	16.80
10/24/2014 Redeye Rentals & Sales Ltd. 17318 PST 3.5 10/31/2014 VIC VAN ISLE CONSTRUCTION LTD 11457 sea can rental 150.0 11/8/2014 Four Season Bobcat & Landscaping 481438 clean up of 8100 building 1.068.0 11/8/2014 Four Season Bobcat & Landscaping 481438 clean up of 8100 building 1.068.0 11/15/2014 HUOLT, SCOTTIE HUO999 7.00 VICVAN 77.50 542.5 11/29/2014 HUOLT, SCOTTIE HUO999 ##### VICVAN 77.50 1.680.0 11/30/2014 Southeast Disposal Ltd 108791 daily waste service Nov 1.180.3 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$ 2 905.9 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$ 2 905.9 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 55.621.2 13/20/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD 1381 1.00 Fence panels 100.0 19/30/2014 VIC VAN ISLE CONSTRUCTION LTD		•	17318		plate tamper rental	50.00
10/31/2014		•			•	3.50
Cost Type GENERAL OVERHEAD	10/31/2014		11457		sea can rental	150.00
Cost Type: GENERAL OVERHEAD	11/8/2014	Four Season Bobcat & Landscaping	481438		clean up of 8100 building	1,066.00
11/15/2014		, -				\$1,526.30
11/15/2014					1	
T7.50 542.5 11/29/2014 HUOLT, SCOTTIE HUO999 #### VICVAN	Cost Type :	GENERAL OVERHEAD				
HUOLT, SCOTTIE	11/15/2014	HUOLT, SCOTTIE	HUO999	7.00	VICVAN	
1/30/2014 Southeast Disposal Ltd 108791 daily waste service Nov 1,180.3 12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$ 2 905.9 12/15/2014 VVICON VICVAN 1.00 Contractor's Fee of 5% of \$ 22,648.91 1,132,4 Total:	3				77.50	542.50
11/30/2014 Southeast Disposal Ltd 108791 daily waste service Nov 1,180.3 12/15/2014	11/29/2014	HUOLT, SCOTTIE	HUO999	#####		
12/15/2014 VVICON VICVAN 1.00 Construction Management @ 4% of \$ 2 905.9 12/15/2014 VVICON VICVAN 1.00 Contractor's Fee of 5% of \$ 22,648.91 1,132.4 Total:, GENERAL OVERHEAD \$5,621.2 Cost Type: MATERIALS 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 11/11/2014 Invermere Hardware & Bldg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bldg Supp Ltd. 303741 PST 3.7 11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 PST 57.4	1					1,860.00
12/15/2014	11/30/2014	Southeast Disposal Ltd	108791		daily waste service Nov	1,180.35
Cost Type : MATERIALS 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Sea can 150.0 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 PST 3.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rail for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/25/2	12/15/2014	VVICON	VICVAN	1.00	Construction Management @ 4% of \$ 2	905.95
Cost Type : MATERIALS 9/30/2014	12/15/2014	VVICON	VICVAN	1.00	Contractor's Fee of 5% of \$ 22,648.91	1,132.44
9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Sea can 150.0 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rall for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 Screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0	Total:,	GENERAL OVERHEAD				\$5,621.24
9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Sea can 150.0 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rall for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 Screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0	Cost Time:	MATERIALS				
9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Fence panels 100.0 9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Sea can 150.0 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 PST 3.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rall for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 Screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0			11381	1.00	Fence panels	100.00
9/30/2014 VIC VAN ISLE CONSTRUCTION LTD 11381 1.00 Sea can 150.00 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 3.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rall for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0					•	
11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 homecrete concrete mix 53.2 11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 PST 3.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rail for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/25/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0 <td></td> <td></td> <td></td> <td></td> <td>'</td> <td>150.00</td>					'	150.00
11/11/2014 Invermere Hardware & Bidg Supp Ltd. 301411 PST 3.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rail for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0				1.00		53.20
11/17/2014 Invermere Hardware & Bldg Supp Ltd. 303741 hardboard 7.7 11/17/2014 Invermere Hardware & Bldg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 rall for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0		•				3.72
11/17/2014 Invermere Hardware & Bidg Supp Ltd. 303741 PST 0.5 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bidg Supp Ltd. 304034 rail for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/25/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bidg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0		- , ,				7.74
11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 PST 57.4 11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 rail for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0						0.54
11/17/2014 Invermere Hardware & Bldg Supp Ltd. 304034 rail for glass 820.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0		•				57.40
11/21/2014 SKANDIA CONCRETE 4-7310-05110 front slab repairs 293.0 11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bldg Supp Ltd 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd 314242 wall brackets 180.0		-				820.00
11/21/2014 SKANDIA CONCRETE 4-7310-05110 PST 20.5 11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0		- , ,			•	293.00
11/25/2014 Canmark Roofing 11282014 torch on roofing to machine room roof 1,240.0 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0					•	20.51
11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 PST 1.1 11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0					torch on roofing to machine room roof	1,240.00
11/25/2014 Invermere Hardware & Bldg Supp Ltd. 307218 screws & paint 16.3 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bldg Supp Ltd. 314242 wall brackets 180.0		<u> </u>			•	1.14
12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 PST 12.6 12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0		•				16.30
12/11/2014 Invermere Hardware & Bidg Supp Ltd. 314242 wall brackets 180.0					•	12.60
					wall brackets	180.00
	Total:	MATERIALS				\$3,056.15

1			i,	
Cost Type :	SUBCONTRACTOR			
11/14/2014	Interoute Construction Ltd	100850	pavement patching - 50mm hot mix	2,200.00
11/28/2014	Full Mason Enterprises Ltd.	157	finish scratch coating for stone and stu	1,770.00
11/28/2014	Full Mason Enterprises Ltd.	157	framing ;	2,060.00
11/28/2014	Full Mason Enterprises Ltd.	157	stucco	4,867.50
11/30/2014	Resort Villa Management Ltd	SVV-8100N	Concrete - 16.0 Reg Hours	739.36
11/30/2014	Resort Villa Management Ltd	SVV-8100N	Concrete - 18.0 Reg Hours	831.78
11/30/2014	Resort Villa Management Ltd	SVV-8100N	Cultured Stone - 16.0 Reg Hours	739.36
11/30/2014	Resort Villa Management Ltd	SVV-8100N	Stucco - 8.0 Reg Hours	369.68
12/15/2014	Invermere Glass Ltd	13199	S & I Railing Glass	905.93
Total:	SUBCONTRACTOR			\$14,483.61
·			Sub Total:	\$24,687.30
			Holdback @ 10% on Subtotal:	2,468.73
4			Sub Total:	\$22,218.57
			GST @ 5%:	1,110.93
				1,110.00
			Invoice Total :	\$23,329.50
Total :	13523-8100 Sun Chaser Vacation	ı Villa's Building 8100		
,	oun chaser vacation	i vina s bunding 0100	Invoices paid by RVM Total Payable:	(2,814.19) \$20,515.31



Assessment Department Location Mailing Address

PO Box 5350 Station Terminal Vancouver BC V6B 5L5

6951 Westminster Highway Richmond BC V7C 1C6 www.worksafebc.com

Clearance Section

Telephone 604 244 6380 Toll Free within Canada 1 888 922 2768 Fax 604 244 6390

LTA Consultants Inc. 905 - 1708 Dolphin Avenue KELOWNA, BC V1Y 9S4

January 03, 2015

Person/Business: VVI CONSTRUCTION LTD. 817749 AQ(061)

We confirm that the above-mentioned account is currently active and in good standing.

This firm has had continuous coverage with us since January 01, 2009 and has satisfied assessment remittance requirements to January 01, 2015.

The next payment that will affect this firm's clearance status is due on January 20, 2015.

This information is only provided for the purposes of Section 51 of the Workers Compensation Act, which indicates that a person using a contractor or subcontractor to perform work may be responsible for unpaid assessments of the contractor or subcontractor.

Employer Service Centre Assessment Department

Clearance Reference #: C128120734

CLRA1A

Now you can report payroll and pay premiums online. Visit www.worksafebc.com

SCHEDULE – 'C' PROGRESS PHOTOGRAPHS





1. Front Elevation Showing Canopy Removed & Stucco Repairs



2. Front Elevation Showing Canopy Removed & Stucco Repairs



3. Asphalt Patching Where Columns Removed



4. Asphalt Patching Where Columns Removed



5. 3rd Floor Balcony Edge Repairs



6. 3rd Floor Balcony Edge Repairs






7. Elevator Machine Room Roof




8. Concrete Patching Where Column Removed



9. New Concrete Slabs-on-Grade to Rear Patios



10. New Concrete Slabs-on-Grade to Rear Patios



11. New Concrete Slabs-on-Grade to Rear Patios



12. New Concrete Slabs-on-Grade to Rear Patios

